

REPORT ON THE SLIPPING OF SWAN

17/09/13

Works undertaken on Swan

Pressure wash and sand anti-fouling

Razing of water line to accommodate change in static trim.

Replacement of anchor bow sprit

Re-seating and bracketing of bilge float switch

Repair of holes in hull

Rudder removal, re-bushing of bottom gudgeon, shimming of upper gudgeon and pintail.

Re-alignment of tiller

Cleaning and grinding of propeller, sealing with silicon preparation to stop fouling.

Replacement of zinc anodes

A Big thank to:

Andrew Giles, Stephen Lee, Colin Gibbs, David Hatton, John Barry, Jean Monger.

SAILING COMMITTEE